



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

0001

Inspection Report
Minerals Regulatory Program
Date: October 23, 2008

Reviewed: Ed

Mine Name: T & M Holdings	Permit Number: S/035/0023
Operator Name: Decorative Landscaping Inc. <u>2</u>	Inspection Date: 10/16/2008
Inspector(s): Brett Gregory for Leslie Heppler	Time: 1:30 pm
Other Participants: None	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Amount: \$19,000.

Permit fee: Current.

Purpose of Inspection: This was a routine annual inspection of the site.

Inspection Summary: Photos attached.

5) I spoke with Bob Anderson about the road being made furthest to the west; and he stated that a 60 ft. wide road would be built where his disturbance was. Road construction is not exempt from needing a bond in place. Until the transition from mining to development has been made, T& M Holdings will need to provide a bond to cover the cost of a new disturbance.

6) With this permit covering so much scattered area, the NOI needs to be updated showing any recent mining activity, along with a new map showing any changes. Technically, the three mining permit areas should be permitted as a large mine.

Conclusions and Recommendations: Changes in the mine plan must be submitted and approved by DOGM prior to implementing them. Operator needs to submit annual reports as required. Including recent maps which show the current status of the mine. It would be easier and more cost effective to permit a large mining operation (LMO) with the amount of acreage disturbed, or possibly begin concurrent Reclamation for the post mining use.

Inspector's Signature

BG:vs

cc: Tracy Burnham

O:\M035-SaltLake\S0350023-DecorLandscape\inspections\insp-10162008.doc

0001



New disturbance not bonded for



Road disturbance that Bob stated was being blazed for county road dozers.



Southern view of where a 60 ft. wide road was to be built



Two road types below his disturbance and proposed road survey site.



Mining



Rock crushing equipment seen on site



Possible location for development



Another view of possible development area



Area Bob mentioned that he was going to reclaim.



Road to first disturbance of many in permit S0350023.



Southern view



Northern view



Furthest west S0350023 disturbance.



Stockpiles from reclaimed areas.



Northeast view of stockpiles and road passage.



Extent of stockpiled material.